Data Sheet
uniortools.com

Pro chain wear indicator

1643/4

Usage

Profiles

(/eng/support/waranty)

Product features

How to use the tool:

- To alleviate poor shifting and uneven drive train wear, most manufacturers recommend chain replacement at or before 0,6% stretch. Now you can quickly and accurately determine the wear and stretch of any chain. Simply insert the chain checker`s pins into two links, press the swing arm gauge tight, and then check the gauge window for an accurate reading.

		L	B	A			
617170	0 - 1,2	137	25,5	20	119,4	120,6	168



Retail packaging

	MA	MB	MC	
617170	185	54	28	238

Transport packaging

		TA	TB	TC	
617170	1				